

BUILDING SAFETY CERTIFICATE

1. It is certified that the building No Adm Block, 2A, 3A, 4A G.F &.F.F Blocks of Army Public School, Near Army Recruiting Office, Ferozepur is found sound by visual inspection.
2. The above said building is structurally found sound by visual inspection.

AGE B/R-I (West)

Ferozepur Cantt

GE (West)

Ferozepur Cantt

File No _____

